

TriQuint Semiconductor, Inc.

RoHS Exception List

April 2007

TQ8710
TQ8319
TQ5122
CMY91
CGY196
CGY121B
CFY35
CFH120
CF739(R)
CHIP T 431Y
CMH192
TC-8003-BS
TC-8004-BP
TC-9203-AJ
TQ3M31
TQ3131
TQ3132
TQ3631
TQ3632
TQ5131
TQ5132
TQ5135
TQ5631
TQ5635
TQ-9132-BN
TQ-9223-C
TQP2420